

# Field Termination Plug User Guide

**1**

Copper Foil Tape  
30mm  
10mm

**2**

Boot  
Cable

**3**

30mm Min.  
10mm  
or  
10mm  
30mm Min.

S/FTP  
U/FTP.F/UTP

**4**

10mm  
30mm Min.  
Copper Foil Tape

**5**

7/8 4/5  
3/6 1/2

4/5 7/8 1/2 3/6

7/8 4/5 1/2 3/6 ✓

7/8 4/5 1/2 3/6 ✗

**6**

**7**

5~8mm Max.

**8**

Cut 2  
Cut 1  
0.2mm Max.

**9**

Align

**10a** Hand screwing

1  
Close

**10b** Optional Tool

1  
2

**11**

Grip 1  
2 Screw

**12**

	Solid	Stranded	Wire (O.D.)	Cable (O.D.)
C6 <sub>A</sub> /C7	23~26AWG	23~26AWG	1.0~1.4mm	6.0~7.5mm
C8	22~24AWG	22~24AWG	1.2~1.7mm	7.0~8.5mm